

**Part – I**  
**Perform for the Safety of School Building**  
**(To be filled by the Head of School/ Institute)**

1)	Name of The School		Kalgidhar Academy Sen Sec School Dugri
2)	Location		Vill. Dugri Near Sahnewal Distt Ludhiana
3)	Plot Area		8 Acre
4)	Plinth Area		Ground/Floor 25497 Sft First /Floor 23212 Sft Total area in Mtrs:-4525
5)	Number Storey		Two
6)	Year of Construction of building		1997,2002&2016
7)	Supervisor of the qualified Engineer, the following details may be given:		N.A
	a. Name of Engineer:		N.A
	b. Address		
	c. Set of Structure Drawing used in construction if available		Plan Attached
	d. Name of the Architect		Er Rajan Tangri (IDEAS'HUB) 45-H, Sarabha Nagar, Ludhiana.
8)	Whether the building has been construct red for the purpose of:		
	a. School	(YES/NO)	Yes
	b. Residential Purpose and converted for use as school	(YES/NO)	No
9)	Materials used for roof:		
	a. R.C.C. Slabs	(YES/NO)	Yes
	b. R.S. Joists and Battens	(YES/NO)	No
	c. Wooden Joists and Battens	(YES/NO)	No
10)	Materials used for walls:		
	a. Mud Mortar	(YES/NO)	No
	b. Cement Mortar	(YES/NO)	Yes
	c. Plaster (i) Lime Mortar	(YES/NO)	No
	(ii) Cement Mortar	(YES/NO)	Yes
11)	Flooring:		
	a. Conglomerate	(YES/NO)	Yes
	b. Terrazzo	(YES/NO)	No
	c. Brick Paving	(YES/NO)	No
12)	Detailed Drawing indicating dimensions of the rooms along with size and location of doors and windows		Attached



Signature with Stamp of  
The Head of the School/Institute

Principal  
**KALGIDHAR ACADEMY**  
 Sen. Sec. School-Dugri  
 Affiliated to CBSE Vide Affi. No. 1631043

**Part – II**  
(To be filled by S.D.F. of P.W.D.B & R Department)


I have visited the above mentioned school on 22/6/24 and have visually inspected it from all angles of safety and found it fit for normal use as school building

In case any addition/alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of technically specified Engineer and this certificate may again be obtained after completion of work from the undersigned.

In case of the building is affected by flood or if there is settlement of walls/foundation or eaves of roof etc. immediately inspection of undersigned be arranged to check the stability and safety of the building.

This building can be safely occupied for normal use up to 31-3-25 (Indicate year up to which it can be used).

B  
AE

  
ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ  
ਪ੍ਰਾਤਕ ਉਪ ਮੰਡਲ ਨੰ: 2  
ਭ ਤੇ ਮ ਸਾਖਾ, ਲੁਧਿਆਣਾ।