

Part – I
Perform for the Safety of School Building
(To be filled by the Head of School/ Institute)

1)	Name of The School	Kalgidhar Academy Sen Sec School Dugri
2)	Location	Vill. Dugri Near Sahnewal Distt Ludhiana
3)	Plot Area	8 Acre
4)	Plinth Area	Ground/Floor 28100 Sft First /Floor 23212 Sft Total area in Mtrs:-4767
5)	Number Storey	Two
6)	Year of Construction of building	1997,2002&2016
7)	Supervisor of the qualified Engineer, the following details may be given:	N.A
	a. Name of Engineer:	N.A
	b. Address	
	c. Set of Structure Drawing used in construction if available	Plan Attached
	d. Name of the Architect	Er Rajan Tangri (IDEAS'HUB) 45-H, Sarabha Nagar, Ludhiana.
8)	Whether the building has been construct red for the purpose of:	
	a. School	(YES/NO) Yes
	b. Residential Purpose and converted for use as school	(YES/NO) No
9)	Materials used for roof:	
	a. R.C.C. Slabs	(YES/NO) Yes
	b. R.S. Joists and Battens	(YES/NO) No
	c. Wooden Joists and Battens	(YES/NO) No
10)	Materials used for walls:	
	a. Mud Mortar	(YES/NO) No
	b. Cement Mortar	(YES/NO) Yes
	c. Plaster (i) Lime Mortar	(YES/NO) No
	(ii) Cement Mortar	(YES/NO) Yes
11)	Flooring:	
	a. Conglomerate	(YES/NO) Yes
	b. Terrazzo	(YES/NO) No
	c. Brick Paving	(YES/NO) No
12)	Detailed Drawing indicating dimensions of the rooms along with size and location of doors and windows	Attached

Signature with Stamp of
The Head of the School/Institute

B. B. Kaur

Ms Bhupinderjit Kaur
Principal
KALGIDHAR ACADEMY
Sen. Sec. School Dugri
Affiliated to CBSE Vide Aff. No. 1631043

Part – II
(To be filled by S.D.F. of P.W.D.B & R Department)

I have visited the above mentioned school on 23/5/25 and have visually inspected it from all angles of safety and found it fit for normal use as school building

In case any addition/alteration of expansion and modification of this building is to be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case of the building is affected by flood or if there is settlement of walls/foundation or caves of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.

The Area as written in the application form has been verified and found correct as per site.


The fee submitted is correct as per built up area of School and Govt. notification for fees.

The fee submitted by the School has been verified on portal.

This building can be safely occupied for normal use up to 31-3-26 (Indicate year up to which it can be used).


AE

Sub Divisional Engibneer


Sub Divisional Engineer
Provincial Sub Division No.2,
PWD, B&R Br., Ludhiana